#### SINGLETREE DESIGN REVIEW COMMITTEE MEETING MINUTES March 13, 2008

A Regular Meeting of the Singletree Design Review Committee was held on Thursday, March 13, 2008, at 8:30 a.m., at the Singletree Community Center, Edwards, Colorado.

The members present were: Chairman George Gregory, Connie Powers, Charlie Dolan and Karen Woody. The Architectural Consultant, John Perkins, was also in attendance.

**MEETING MINUTES** – The Committee reviewed the February 28, 2008 meeting minutes. By motion duly made and seconded, it was unanimously

**RESOLVED** to approve the February 28, 2008 meeting minutes as submitted.

# Merritt ResidenceLot 6, Blk. 4, Flg. 4Final Review0520 Winslow RoadFinal Review

Alicia Davis presented the final plans to the Committee for their review and the following matters were noted:

- a. A landscape plan is required.
- b. The color board is incomplete and a sample of the siding stain is required.
- c. Meters must be concealed and integrated into the building.
- d. Mechanical flues must be enclosed in a chimney chase and noted on the drawings.
- e. Note on the plans that the crawl space will not exceed 5 feet.
- f. Details on the trusses and knee braces are required.
- g. Details on the deck handrail is required.
- h. The proposed exterior lights (at the rear elevation) are not approvable as submitted.
- i. Green, netted, plastic construction fencing is required and must be indicated on the site plan. (Section 6.4)
- j. Flashing details are required.
- k. Construction parking will be an issue. Parking must be on the uphill side and on one side only and must be noted on the plans.
- 1. Stone cap must be an  $2\frac{1}{2}$ " minimum and the type of stone must be called out.

The matter is tabled at the Applicant's request.

#### **Dawsey Residence**

#### Lot 49, Blk. 3, Flg. 4 0060 Bronco Drive

### Remodel

John and Yvonne Dawsey presented the remodel plans to the Committee for their review and the following matters were noted:

- a. The fire pit is to be non-wood burning and will be fueled by natural gas and a note on the plans is required.
- b. The deck post dimensions are 8" x 8".
- c. The glass on the exterior lights must be caramelized. (Section 3.13)
- d. All galvanized metal must be painted out to match the existing.
- e. The dimension of the sandstone cap must be a minimum of  $2\frac{1}{2}$  thick.
- f. The deposit amount will be \$5000.00
- g. Railing details are required.
- h. Erosion fencing and green, plastic, netted construction fencing is required and must be indicated on the site plan. (Section 6.4)

- i. The roof tiles will be a #1 medium cedar shake. (Section 2.9)
- j. After the Applicant receives their fire rating any evergreen trees must be a minimum of 6 t. in height and all deciduous trees must be  $2\frac{1}{2}$  caliper.

Mr. Dolan made a motion to approve the final plans subject to the conditions outlined above. By motion duly made and seconded by Ms. Powers, it was unanimously

**RESOLVED** to approve the final plans subject to the conditions outlined above.

## Molina ResidenceLot 67, Flg. 1Remodel0855 Charolais Circle

Leah Mayer, the architect for the project, presented the remodel plans to the Committee for their review and the following matters were noted:

- a. Detail on the meter gate is required.
- b. The proposed exterior lights are not approvable as submitted. All exterior lights are to be down light and cut sheets are required. (Section 3.13)
- c. All metal is to be painted out.
- d. The quoins on the chimney are to be removed.
- e. Increase the deck rail pickets to .<sup>3</sup>/<sub>4</sub>" to 1".
- f. The spiral staircase is to match the deck rail color.
- g. Erosion control fencing and green, netted, plastic construction fencing is required and must be indicated on the site plan. (Section 6.4)
- h. A new landscape plan is required.
- i. A chimney cap is required.

Mr. Dolan made a motion to approve the remodel plans subject to the conditions outlined above. By motion duly made and seconded by Ms. Woody, it was unanimously

**RESOLVED** to approve the remodel plans subject to the conditions outlined above.

#### **INSPECTION REQUEST FOR JOHN PERKINS:**

Bleesz Residence	Lot 44, Blk. 4, Flg. 4	\$5,000 compliance
	1511 Singletree Road	deposit

**ADJOURNMENT** – The meeting was adjourned at 10:45 a.m.